



Product Release 2.0M1 GA Release Note

Alvarion Ltd. All rights reserved.

The material contained herein is proprietary, privileged, and confidential. No disclosure thereof shall be made to third parties without the express written permission of Alvarion. Alvarion reserves the right to alter the specifications in this publication without prior notice.

Alvarion Ltd www.alvarion.com



1. General

This document details the main hardware elements, software features, and known limitations of 4Motion 2.0M1 GA release.



2. Released Products

4Motion 2.0M1 release is an e-certified release enabling advanced mobility technologies. The system operates in bands 2.3GHz, 2.5GHz, and 3.5GHz TDD (5 MHz and 10 MHz) and is intended for worldwide use (2.3GHz is trial mode).

The product introduced in this release is designed with open architecture and interfaces complying with IEEE 802.16e and WiMAX Forum Technical Working Group (TWG) PHY/MAC Profiles and Networking Working Group (NWG) Profile C. It is designed to support both distributed and centralized topology approaches, thus providing operators with the flexibility to select the mobile WiMAX network topology that best suits their needs and existing network architecture.

The product is Alvarion's market-leading mobile WiMAX solution. Designed with open IP architecture and interfaces, 4Motion 2.0M1 release integrates the most advanced and adaptive radio management and control technologies to optimize operator spectrum and network resource usage.

Maintaining a host of radio and air interface, security, networking and management features, 4Motion 2.0M1 release also introduces seamless handover control and management as well as stringent QoS requirements for next-generation applications.

The product is an end-to-end solution comprising Base Transceiver Station (BTS) equipment, Access Service Network Gateway (ASN-GW), AAA servers, an Element Management System (EMS), and End User Devices.

Leveraging its leadership position in WiMAX and driven by BreezeMAX[™] and now 4Motion, Alvarion's 2.0M1 release is taking the market to the next level – mobile WiMAX.



3. About this Release

4Motion former 2.0 release is a field proven stable release, allowing good radio performance and robust indoor and outdoor capabilities.

The following features & capabilities are **newly** introduced in 2.0M1 release compared to the former R2.0:

- Networking
 - Unmanaged VoIP
 - SLB with Cisco ASN GW
 - Single ALVR ASNGW with multiple BSs
- CPE Types
 - o RGW at 2.5 and 3.5GHz
 - Outdoor CPE at 2.5 and 3.5GHz (CPE GA 31-Dec)
- ODU Types
 - o 2x4 ODU's at 2.5GHz (2.5GHz Band B Hardware GA is 31-Dec)
 - o 2x4 ODU at 3.5GHz

This release is designed as an end-to-end solution based on the following system components:

- BTS equipment with localized integrated and distributed ASN-GW
- Centralized ASN-GW, which may be offered as part of an end-to-end solution that includes Cisco's equipment
- AAA servers provided by Bridgewater Systems and Cisco
- Element Management System AlvariSTAR[™] providing interfaces towards NMS/OSS systems
- End User Devices (PC Cards) provided by AWB as well as Residential Gateways (RGW) and Outdoor CPE BMAX-Pro Unit

The release supports the following main hardware elements:

- AU IDU 4-channels card
- NPU 1GB data interface
- High power ODU supporting 38dBm in the 2.x GHz bands and 37dBm in the 3.5GHz band
- 2x4 ODU's at 2.5GHz and 3.5Ghz bands (38dBm and 37dBm respectively)
- Sectorial 65° Dual Slant Polarization RET/EDT Antennas in 2.xGHz



- Sectorial 65° Dual Slant Polarization Antennas in 3.5GHz
- Applicable GPS modules
- GPS cable adaptor
- Base Station clocks synchronization by GPS
- 2.5, 3.5 GHz PC Cards
- 2.5GHz and 3.5GHz RGW and Outdoor CPE.
- The PC Card performs better on a platform with Pentium 1GHz (or higher), 256 MB RAM (or higher) and with DOTNET Framework version 2.0 (or higher) pre-installed.
- EMS x1 Processor: Dual Xeon processors with 800 MHz FSB. RAM & Hard Disk: 2 GB RAM, one or more 10000 rpm SATA or SCSI HDD, min 80GB
- Cisco ASN-GW
 - o CISCO ASNGW Router 7600
 - o AAA Server (CAR) x1 Sun T1000
 - DHCP Server (CNR) x1 Processor Dual Pentium 4 2.4 GHz and above with Hyper Threading RAM & Hard Disk 2 GB, SATA or SCSI hard disk 40GB
- BWS AAA
 - AAA x1 Sun T1000/T2000

Please also refer to CPE 2.0M1 release note for more information



The software versions introduced in this release are:

Product Type	Product Vendor	Product P/N	Release	Comments
DHCP Server	Cisco	CNR	6.2.3.2	
AAA Server	Bridgewater	T1000/T2000	8.2C2	
	Cisco	CAR	4.1.3	
ASN-GW	Alvarion	NPU	1.0.0.23	
	Cisco	7600 IOS	12.4	1.1p
		7300	(280127:045245)	
BS	Alvarion	AU	2.0.11.3	
MS	AWB	PCMCIA/WCM	1.0.11.4	4.1M5.2
	AWB	RGW	0.2.10.3	
	AWB	Outdoor CPE*	0.2.10.3	* CPE GA 31- Dec
EMS	Alvarion	AlvariSTAR EMS Device Driver	2.0.0.27 (Alvarion logo)	With service pack 1
	Alvarion	AlvariSTAR Infrastructure	3.5.1.51	With service pack 4



4Motion 2.0M1 GA release supports the following main features:

■ BreezeMAX Configuration

- 1. BTS antenna 2nd and 4th order diversity
- 2. 2300-2360, 2496-2690, 3400-3600 MHz
- 3. 5MHz, 10MHz channel spacing

Radio Features

- 4. Power Control: Closed and Open loop power control mode
- 5. UL and DL Rate Adaptation
- 6. UL and DL HARQ
- 7. MIMO (Matrix A) STC
- 8. 2 and 4 way UL diversity (MRRC)
- 9. MS spectrum scanning and best AU selection
- 10. Extended Range of 22Km

ASN Features

- 11. Intra-BTS optimized Hard HO
- 12. Inter-BTS optimized Hard HO
- 13. R6 Profile C
- 14. Fast R8 for mobility control
- 15. ASN Diffserv, 802.1p marking policy
- 16. Distributed and Centralized ASN architectures
- 17. IPv4 CS

Network Features

- 18. Mobile services
- 19. Authentication Methods: EAP-TTLS (including user/password verification)
- 20. Unmanaged VoIP



- 21. SLB with Cisco ASN GW
- 22. Centralized ALVR ASN-GW with multiple BS's

Alvarion ASN-GW Features

- 23. Two DHCP modes:
 - DHCP Relay
 - DHCP Server
- 24. Simple IP
- 25. R3 Radius: Authentication, Authorization, Accounting
- 26. Post Paid Accounting
- 27. IPoIP tunneling on R3 northbound



EMS Features

28. FM:

Event Monitor and Event History

29. CM:

- Equipment Manager
- Network Discovery
- Device Synchronization

30. PM:

- Real time performance monitoring
- Performance Collection

31. Security

User and permission management

32. System Utilities:

- Task Manager
- Software Upgrade
- AlvariCRAFT configuration tool (AlvariSTAR on laptop)
- Northbound Interface to OSS
- Online help

WiMAX Devices

- 33. PC Card in 2.5, 3.5GHz
- 34. Residential Gateways (RGW) in 2.5, 3.5GHz
- 35. Outdoor CPE BMAX-Pro in 2.5, 3.5GHz

Network Ecosystem

36. ASN-GW:

- Distributed ASN Alvarion ASN-GW
- Centralized ASN Cisco ASN-GW 7600 & 7300



37. AAA:

- Bridgewater Systems for Alvarion ASN-GW
- Cisco CAR for Cisco ASN-GW



4. Documentation

There are four manuals released with this GA. Each manual covers all relevant topics associated with the respective component, including:

- System Manual, comprising the following main chapters:
 - 1. Product/Solution Description
 - 2. System Installation
 - 3. Commissioning
 - 4. Operation and Administration
- 4Motion Installation Manual (detailed step by step installation instructions)
- AlvariSTAR 4Motion Device Manager User Manual
- 4Motion End User Devices documentation (not part of BS documentation) :
 - 1. PC Card: Product Manual & Technical Specification, Quick Installation Guide
 - 2. RGW: Product Manual & Technical Specification, Quick Installation Guide
 - 3. CPE Pro: Product Manual & Technical Specification, Quick Installation Guide



5. Outdoor CPE: Technical Specification, Product Manual, Quick Installation Guide Known Limitations

1. General Limitations

1. 2.0M1 release supports up to 95 End User Devices per AU/Sector as was tested (theoretical limit is 168)

BreezeMAX Product Limitations

- In rare occasions the NPU card does not respond and may lose network connectivity; this usually causes an automatic reset after which the system operates properly. A manual reset is required if an automatic reset does not occur.
- 2. During NPU or AU software download no NPU maintenance/configuration activities are to be performed as it might lead to an NPU reset.
- 3. Reduced performance with Encryption and HARQ has been indicated

Radio Limitations

 Rarely, in deployments larger than 16 BTS's, a laptop might freeze when it recognizes a BTS not included in its own neighbor list. In such cases an MS reset is required.

■ ASN-HW Centralized NPU Limitations (worst case of the below shall be applied)

- 1. Centralized NPU can support up to 3000 MS's
- Centralized NPU aggregated throughput for its served BS's, should not exceed 220Mbps (DL+UL) for all MS QoS types (accumulating BE, UGS, RT) as no traffic statistics nor shaping is performed on NPU side
- 3. Note for example, that in a typical network of 7 BS with a total of 21 AU sectors cards, above limitations may be reached. In such case careful attention should be taken considering aggregated MS traffic. For example for the DL, traffic shaper may be used at NPU ingress from CSN into its northbound interface (e.g. 165Mbps DL from CSN), where for the UL total aggregated MS's service flows capacity will not exceed 55Mbps in case of 3:1 DL:UL ratio (165Mbps:55Mbps) so the total 220Mbps limitation will not be exceeded.



Centralized ASN-GW Cisco 7600 Limitations

ASN-GW load balancing with Cisco 7600 is not operational and is under investigation

 update will be provided within couple of days (this issue does not occur with Cisco 7300 ASN-GW)

EMS Limitations

- 1. NPU clock time should not be changed backward during a PM collection.
- 2. In order to allow the download of a 'Vendor Configuration' file, the file should be installed on AlvariSTAR server file system and not on AlvariSTAR database.
- 3. Configurable parameters defining a range (e.g. high / low values) should be configured separately. When a configurable range is going up, the higher value is to be configured first; when a configurable range is going down, the lower value is to be configured first. The system will not function properly if these guidelines are not addressed.
- A partial addition operation of a record, created via CLI, will not be implemented in EMS and will affect EMS performance; users are requested to complete the record addition operation via CLI.
- 5. When performing a configuration change via AlvariSTAR the user should wait 15 minutes between the last configuration change and a reboot from shadow, otherwise configuration changes performed during this period will be lost.
- A configuration manager tree refresh is done by re-opening the configuration manager (e.g. when adding a new BTS) in order to reflect changes made via CLI or any other AlvariSTAR client.
- 7. Site VLAN configuration, bearer VLAN ID parameter, must not be touched if NPU is operating in a transparent mode configuration (if these guidelines are not met a general error might pop up in AlvariSTAR display).
- 8. In order to collect historical performance records always refer to 'BM4M Performance Collection' task in AlvariSTAR Task Manager and not to 'Performance Collection' task.
- 9. Aging process associated with 'Performance Collection' task is not fully supported; system administrator will need to remove aged files.



- 10. In AlvariSTAR main menu window the 'Provisioning' sub-tree is unused (in future this sub-tree will be removed).
- 11. When maintaining Reference Classification for ASN-GW Service Profiles Rules, the rules should be deleted first and then re-entered.
- 12. EMS presents only one connected ODU, although two or four are actually connected.
- 13. When upgrading the software and using 'External Client' mode on Solaris OS, users will need to select 'AlvariSTAR' for the 'External Client'.
- 14. CLI is to be used for configuring QoS ACL 199.
- 15. When setting the connectivity L1/L2, 'Bearer VLAN ID' and 'External Management VLAN ID' should not carry the same value.
- 16. The EMS system allows exporting a single backup file from the File Manager.
- 17. The 'Single File' box in the 'Action' tab of 'Performance Collection' task should always be checked.
- 18. Multiple Service Flows should not be deleted simultaneously but rather each at a time.
- 19. '7 MHz' for Bandwidth should not be selected (this bandwidth is not supported in 4Motion 2.0 release).
- 20. When changing 'Community Strings', running a 'Network Scan' task is required in order to trigger EMS reconnection.
- 21. In order to change a 'Backup' task type from current configuration to an older one, a new Backup task creation is required.
- 22. In some cases, when modifying the 'BTS Services Mapping' to an alphanumeric character value, a general error message is displayed.
- 23. When changing the Site name in the 'Equipment Manager' screen, the associated backup files are not deleted.
- 24. The deletion of multiple devices from the 'Equipment Manager' screen should be avoided.
- 25. When adding an ACL connectivity rule and double-clicking the ACL name, a general error message appears.



- 26. When setting a 'Discovery Network' process, entering the existing 'Community String' should be avoided.
- 27. When modifying the 'Bandwidth' parameter from 10MHz to 5MHz, sub channel values associated with the new 'Bandwidth' value should be modified and applied first, and only then the 'Bandwidth' parameter should be assigned with the new value.
- 28. When configuring standard ACL, users can modify the following parameters: Source IP Address, Source IP Mask, Destination IP Address, Destination IP Mask, and Rule Action. All other standard ACL parameters should not be modified.
- 29. Changing the value parameter of 'Map Repetition' takes affect only after AU reset.
- 30. For 'Bandwidth' value of 10MHz, the correct sub-channels range is 11 to 17 (and not 1 to 17)
- 31. The following parameters displayed in 'BS>Radio>Advanced>Handover' tab should not be modified:
 - MS Handover Retransmission Timer
 - Handover Default Action Time
 - Fast Ranging Allocations
 - Periodic Interval
- 32. The following parameters displayed in 'BS>Radio>Advanced>Scanning' tab should not be modified:
 - Min. BW Degradation Factor
- 33. EMS supports upgrade of AU and NPU cards on Windows only and not on Solaris Platform. Upgrade is possible with Solaris using Telnet.

CPE Limitations

For specific CPE limitations please refer to CPE 2,0M1 release note.



Detailed Bug List

#	Detail	Workaround	Known from Release	Solved in Release
NPU				
STR11481	AU - Error 67 No communication to NPU, NPU requires reset - rarely happens		2.0M1	TBD
STR14845	IP Packet size 1026 bytes cause DL throughput degradation	Happens mainly in point to point testing mode, rarely happens in real point to multi point networks	2.0M1	2.5M1 Tentative
STR14177	NPU doesn't save AlvariSTAR parameters after reset via CLI	Before reset one should 'write' save the configuration.	2.0M1	TBD
STR13666	Centralized ASN-GW NPU – Rarely the uncontrolled HO doesn't work properly		2.0M1 Beta	TBD
STR14982	Centralized Cisco 7600 ASN-GW load balancing not operational	Under investigation, update within few days	2.0M1	TBD
AU Bugs				
STR13689	MS stops doing intra HO after 20 minutes of successive HO's. (after 150 HO's)	Waiting for chip vendor inputs	2.0M1 Beta	2.5 (Tentative)
STR14410	Degradation in downlink throughput during MS scanning when HARQ and Encryption are activated		2.0M1	2.5 (Tentative)
STR14929	In bad link conditions very rarely an AU performs reset (fpga)		2.0M1	TBD



Solved Bug List (from earlier releases)

#	Detail	Known from Release	Solved in Release
NPU			
STR12951	NPU SW upgrade process doesn't work correctly	2.0M1 Beta	2.0M1
STR12979	GPS: NPU does not stop AU once Holdover times out	2.0M1 Beta	2.0M1
STR13394	Centralized NPU - It's impossible to manage the NPU while traffic (Short packets)	2.0M1 Beta	2.0M1
AU Bugs			
STR13671	MS can't do NE far then 8 km from BS	2.0M1 Beta	2.0M1
STR13662	Voice traffic (eRT) in UL with bad radio link doesn't work. Checking cell coverage specification.	2.0M1 Beta	2.0M1